INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

GEOSERVE DRILLING SERVICES

PROJECT REPORT UPDATE - CIMERA KARIN PROJECT - ZANDFONTEIN 89



INTEGRATED MANAGEMENT SYSTEM (IMS)

- OHSAS 18001:2007
- ISO 9001:2008
- ISO 14001:2004
- ISSUE BASED RISK ASSESSMENT
- ENVIRONMENTAL IMPACT ASSESSMENT

SEPTMEBER 2015

PROJECT TEAM

N. MOGRIDGE - OPERATIONS MANAGER

E. CROUS - SHE MANAGER

E. VD BERG - SITE MANAGER 2.6.1

A. BIRCH - CLIENT REPRESENTATIVE 2.6.1

Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 1 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

16/07/2015

Mobilizing Equipment to site – Zandfontein. Pre - discussion with crew relating to access roads and Environmental Impact.



16/07/2015

Discussion with Client Environmental Representative and induction program. Geoserve internal induction program with client with regards to Operational Hazards and Environmental Impact. Occupational Health, Safety and Environmental Document Audit Client. Positive feedback from Client representative.



Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 2 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015


ACTIVITY

17/07/2015

Site Establishment. Emphasis on spillage prevention. All equipment placed on plastic liner in order to contain any accidental spill etc. Issue Based Risk Assessment discussed with crew member and register completed.

Sump Skip system located in area where all drill sludge can be bagged and transported to Enviroserve located in Cape Town

Started pumping water - avg. 3600I / hour.





17/07/2015

Project No.:

Form Ref.:

Area demarcated in order to prevent any stray animal entering. Environmental Spillkit located at entrance.

GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN

First Aid Station located at entrance.



CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Page:

3 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

18/07/2015

Complete Site set up – demarcation, Emergency Procedure, Waste Control, Core Yard, Site office.



19/07/2015

DRILLING - START HOLE PQ3 - Drilled 3m



GEOSERVE

Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 4 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

20/07/2015

Drill PQ3 to competent rock formation in order to ream 5'9/16 insert 141mm casing.



21-22/07/2015

Continue drilling PQ3 to competent rock formation in order to ream 5'9/16 insert 141mm casing.

Hole current depth 59.8m.



Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 5 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

23/07/2015

Grouted hole 60m. Waiting for cement to dry 24/07/2015. Installed Burn out pit in case of gas blow out.

24/07/2015

Site visit Aubrey Withers for Environmental Inspection. Prof N Beukes visit.











Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 6 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

25/07/2015 - Started Drilling HQ

29/07/2015 - Drilling: Hole Depth 196m. Struggling with broken formation

3/08/2015

Drilling - Hole depth 240m. Cleaning Sumps and bagging sludge for removal





4/08/2015- Hole Depth 269m. Struggling with broken formation.

NOTE: Currently running on a single shift due to exdtreme weather conditions at night. Production target may have to be adjusted. Will advise in due course.

Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 7 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

09/08/2015

Drilling - Hole Depth 430m through white hill.No traces of CH4





11/08/2015

Drilling – Hole Depth 476.10m. No traces of CH4.Geologist Aleck Birch states that Prince Albert disposition is about 120m and would need 20m dolomite formation over

EOH estimated at 630m >

Daily production avg. 40m est. hole completion Friday 14 August 2015





Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21 Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 8 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

ACTIVITY

27 AUGUST 2015 - HOLE COMPLETED END OF HOLE 671M. CREW ON BREAK TO RETURN ON 7 SEPTMEBER 2015

29 AUGUST 2015 – DOWNHOLE SUREVY COMPLETED

7 SEPTMEBER - START PLUGGING HOLE.

12 SEPTMEBER - HOLE PLUGGED AND REHAB COMMENCED





Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 9 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

14 - 16 SEPTEMBER 2015 - CONTINUE SITE REHABILITATION





17 SEPTMEBER 2015 - FINAL SITE VIST AUBREY WITHERS

GEOSERVE

Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 10 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015

FOCUS AREA RESULTS

CONCLUSION / NEXT STEP

- Site Managers / Supervisors to focus on pre shift toolbox talks and Risk Assessments. Coach Employees daily with regards to EMP and any impact.
- Conduct Safety and Environmental Awareness sessions put emphasis on preventative actions in order to reduce risk and Environmental Impact

MANAGEMENT TEAM	SIGNATURE	DATE
C MOREL - COO	and the second s	21/09/2015
TE CROUS - SHEQ MANAGER		21/09/2015
S MOGRIDGE - CEO	No. of the second secon	21/09/2015

GEOSERVE


Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 11 of 12



INTERNAL AUDIT TEAM SUMMARY

SPECIAL REPORT
QUALITY AND SHE
SHEQIA01/2015



Project No.: CIMERA KARIN PROJECT – ZANDFONTEIN 89 Date: 2015/09/21

Form Ref.: GEOSERVE SAFETY, ENVIRONMENTAL AND QUALITY PLAN Page: 12 of 12

